





















<b>Epoxy/Glass Kit for a typical 16' boat (quantities and some contents vary with size of boat)</b>				
Epoxy kits are a healthy starter kit - depending on usage more may be reuired - reordering is easy - text us what you need				
<input type="checkbox"/>	1 SilverTip Epoxy Resin, gallon		glassing and coating	ea
<input type="checkbox"/>	1 SilverTip Slow hardener, 1/2 gal		med/fast available for colder temps	ea
<input type="checkbox"/>	1 Adhesive Gelmagic Silvertip 3 qt		Structural gluing	ea
<input type="checkbox"/>	1 Quick Fair 1.5 qt kit		Cosmetic filling and fairing	ea
<input type="checkbox"/>	2 <a href="#">Plunger Pump</a>		dispensing resin and hardener	ea
<input type="checkbox"/>	3 1 pint / 16oz graduated cup		mixing an measuring	ea
<input type="checkbox"/>	2 12 oz. mixing cups		mixing an measuring	doz
<input type="checkbox"/>	20 FG tape 2"		bottom inside and outside seams (varies boat to boat)	yd
<input type="checkbox"/>	1 4 oz. cloth 60"		trunk insides	yd
<input type="checkbox"/>	2 6 oz. cloth 38"		foils	yd
<input type="checkbox"/>	10 6 oz. cloth 38"		bottom inside and outside sheathing	yd
<input type="checkbox"/>	0.5 Plastic squeegee		glassing and coating	doz
<input type="checkbox"/>	2 Tongue depressors		mixing, small fillets	pack50
<input type="checkbox"/>	2 1" chip brushes		spreading glue	pack of doz
<input type="checkbox"/>	2 Extra thick chip brush 3"		coating and glassing	ea
<input type="checkbox"/>	1 3" roller frame		glassing and coating	each
<b>Ships from Maine</b>				
<input type="checkbox"/>	1 tapping screw S/S FH sqdr #8x3/4"		general construction	bx
<input type="checkbox"/>	1 1.5 Qt kit of FLAG		gluing scarf joints	ea
<input type="checkbox"/>	2 MAS Woodzilla		filleting	each
<input type="checkbox"/>	1 West Sys mixing sticks (pack of 5)		filleting, cleaning up glue, mixing (reusable)	pack
<input type="checkbox"/>	2 7" foam roller cover		glassing and coating, painting	pack
<input type="checkbox"/>	1 Vial of graphite powder, 4oz.		added to ST epoxy for foils, bottoms	each
<input type="checkbox"/>	1 Syringes		filling screw holes, cracks	